

# **School Radon Testing Reporting Form**

According to Minnesota Statute 123B.571 subd. 3, a school district that has tested its school buildings for the presence of radon shall report the results of its tests to the Department of Health. Please use this form to submit information about the most recent round or cycle of testing conducted for each building.

#### Instructions

- 1. Complete one form for each building tested. In this case, a building is defined as an occupied facility with a unique address. This includes administrative buildings.
- 2. Include this form, raw data (e.g. laboratory report) and a building map.
- 3. Submit this form when all work is completed for a round of testing. This includes reporting to the school board, and follow-up testing and post-mitigation testing, if applicable.
- 4. Email information to <a href="mailto:health.indoorair@state.mn.us">health.indoorair@state.mn.us</a>.

## **Contact Information**

Name: Wendy German	
9	Douglas Rd S, Cottage Grove, MN 55016
Phone: 320-224-1908	Email: Wgerman @Sowashco.org

# **Initial Radon Testing Information**

School Building Name: Cottage Grove	Elementary
	ushington County Schools-District 833
Building Address: 7447 65th St S, Cott	age Grove, MN 55016
Test Kit Manufacturer: AIV CHEK	Device Name: Pro Chek
Date of Kit Retrieval (DD/MM/YY): 03/29/19	Length of Test (days): 3
How many rooms were tested? 39	
Does the test period include weekends?	es X No
Does the test period include school breaks or h	nolidays? Yes X No

#### SCHOOL RADON TESTING REPORTING FORM

Were all frequently-occupied ground contact i	rooms tested? <sup>1</sup> X	es No
If no, did you attempt to test all freque test kits were placed in all these rooms		ntact rooms, meaning
How many rooms had results ≥ 4 pCi/L?:		
Were the results reported at a school board m	neeting? Yes X N	scheduled for to upcoming meetir
Follow-up Testing, Mitigation, 8	Report Post-Mitigation	Testing
If one or more rooms tested ≥ 4 pCi/L, please a		
	4	
How many rooms had follow-up testing?:		
Number of rooms with follow-up results	≥ 4 pCi/L:	< 4 pCi/L:
Of the rooms that had test results ≥ 4 pCi/L, h	now many rooms were:	
mitigated by HVAC balancing or operational ch	nanges? :	
mitigated by installation of active soil depress	urization?:	
addressed through other corrective measures	? <sup>2</sup> :	
What was the cost of the installation and/or H	IVAC service work, to mit	igate radon? \$
What is the known or anticipated annual oper	ating cost of mitigation (	estimate)? \$
After radon mitigation, how many rooms were	e retested?:	

≥ 4 pCi/L:

< 4 pCi/L:

Post mitigation results (# of rooms)

<sup>&</sup>lt;sup>1</sup> This includes classrooms, offices, break rooms, laboratories, cafeterias, libraries, auditoriums, gymnasiums, etc. It includes rooms on grade and rooms above unoccupied spaces that are in contact with the ground, such as rooms above storage rooms, crawl spaces, tunnels, and boiler rooms. If only a sample or portion of rooms were tested, then respond with 'no'.

<sup>&</sup>lt;sup>2</sup> 'Other corrective measures' could include moving staff out of a room and making a room unoccupied or trying to seal radon entry points.

#### Radon test result report for:

# COTTAGE GROVE ELEMENTARY

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
9197469	B111	2019-03-26 @ 9:00 am	2019-03-29 @ 9:00 am	$1.1 \pm 0.5$	2019-04-03
9197464	B115	2019-03-26 @ 9:00 am	2019-03-29 @ 9:00 am	$1.1 \pm 0.5$	2019-04-03
9197432	C101	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	$0.7 \pm 0.4$	2019-04-03
9197440	C103	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197439	C104	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197445	C106	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197444	C107	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197443	C108	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197442	C109	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197441	C111	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197436	C112	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197435	C114	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197434	C115	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197433	C116	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197437	C118	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	$0.6 \pm 0.5$	2019-04-03
9197438	C119	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197446	D103	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197447	D108	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197448	D116	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197462	E101	2019-03-26 @ 9:00 am	2019-03-29 @ 9:00 am	< 0.3	2019-04-03
9197457	E103	2019-03-26 @ 9:00 am	2019-03-29 @ 9:00 am	< 0.3	2019-04-03
9197456	E104	2019-03-26 @ 9:00 am	2019-03-29 @ 9:00 am	< 0.3	2019-04-03
9197449	E106	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197450	E107	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	$1.0 \pm 0.5$	2019-04-03
9197451	E108	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197452	E109	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197453	E111	2019-03-26 @ 8:00 am	2019-03-29 @ 9:00 am	< 0.3	2019-04-03
9197458	E112	2019-03-26 @ 9:00 am	2019-03-29 @ 9:00 am	< 0.3	2019-04-03
9197459	E114	2019-03-26 @ 9:00 am	2019-03-29 @ 9:00 am	< 0.3	2019-04-03
9197460	E115	2019-03-26 @ 9:00 am	2019-03-29 @ 9:00 am	< 0.3	2019-04-03
9197461	E116	2019-03-26 @ 9:00 am	2019-03-29 @ 9:00 am	< 0.3	2019-04-03
9197455	E118	2019-03-26 @ 9:00 am	2019-03-29 @ 9:00 am	$0.6 \pm 0.5$	2019-04-03
9197454	E119	2019-03-26 @ 9:00 am	2019-03-29 @ 9:00 am	< 0.3	2019-04-03
9197465	GYM A	2019-03-26 @ 9:00 am	2019-03-29 @ 9:00 am	$0.6 \pm 0.4$	2019-04-03
9197466	GYM C	2019-03-26 @ 9:00 am	2019-03-29 @ 9:00 am	$0.6 \pm 0.5$	2019-04-03
9197428	MAIN OFFICE	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197429	MAIN OFFICE 2	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	$0.6 \pm 0.4$	2019-04-03

### \*\* LABORATORY ANALYSIS REPORT \*\*

April 3, 2019

# Radon test result report for:

# COTTAGE GROVE ELEMENTARY

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
9197463	MEDIA CENTER	2019-03-26 @ 9:00 am	2019-03-29 @ 9:00 am	< 0.3	2019-04-03
9197431	NURSES	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03
9197430	PRINCIPAL	2019-03-26 @ 8:00 am	2019-03-29 @ 8:00 am	< 0.3	2019-04-03

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498